

OUT57851

TOP SECRET 282152Z

1966 FEB 28 22 02Z

25X1

1. THE FM CALIBRATION BOOKS HAVE NOT BEEN RECEIVED AT [] FOR THE PAST SEVERAL MISSIONS. THE CALIBRATIONS CARRIED IN THE CABLES ARE HELPFUL BUT ARE NOT ADEQUATE FOR ERROR ANALYSIS.

25X1

2. IT IS REQUESTED THAT [] SUPPLY [] WITH CALIBRATION BOOKS FOR MISSIONS 4022, 4023, 4024, 4025 AND ALL FUTURE MISSIONS.

25X1

3. UNIT NUMBERS FOR THESE MISSIONS ARE 4022-FM 16R, 4023-FM 23, 4024-FM 24, AND 4025-FM 25. UNIT NUMBERS FOR FUTURE MISSIONS ARE NOT KNOWN.

4. ALL PREVIOUS CALIBRATIONS FOR MISSIONS 4001 THRU 4021 HAVE BEEN RECEIVED AT [] BEFORE THE MISSION WAS FLOWN. THE SAME SCHEDULE SHOULD BE FOLLOWED FOR FUTURE MISSIONS IF POSSIBLE.

TOP SECRET

/END OF MESSAGE/

1 MAR 1966

DISTRIBUTION

By	On	Action
1	16	
2	OS	
	ADMIN	
	SEC DE	
	P&G	25X1
	CD	
	IFD	
	FD	
	FD	
	ICD-ICB	
345	TID	
	IAD	
	PAG	
	DIAX-4	
	SPAD	
	NSA-LG	
	NSA-AP	

Declassification Review by NGA/DoD

GROUP 25X1
Excluded from automatic
downgrading and
declassification

TOP SECRET